ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0733, W0815, W0608, W0634	NA, 2nd Crs	DEFENCE COLONY
Segment No.	**Total Length (m)**	
14/C-W0733/S044532	167.27	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	167.27	77.504765	13.052526	77.505082	13.054005	W0608	W0634

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads & drain at 5th B cross Diffence Colony	1000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender		014-15-000014
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/296/14-15	16/03/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N Shivananda		0.00
Phone No.	**E-Mail ID**	
9901829745		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಸವನಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು
ಬೆಂಗಳೂರು

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0733, W0815, W0608, W0634

Field Inspection Details

Number of Trees	Any Other Information	Name
0		D.S.MANJUNATH

Date of Inspection	Remarks
29/09/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDA	29/09/2016	29/10/2016	COMPLETED
EE	SRINIVAS	29/09/2016	29/10/2016	COMPLETED
AEE	RANGASWAMY	29/09/2016	29/10/2016	COMPLETED
AE	D.S.MANJUNATH	29/09/2016	29/10/2016	COMPLETED
AE	D.S.MANJUNATH	29/09/2016	29/10/2016	COMPLETED

Zone: DASARAHALLI

Ward No: 14

Ward Name: Bagalakunte

Street ID: W0733, W0815, W0608, W0634